

Hap Firmware Release Notes

Release Date:	2022.11.05
Version:	LIVOX_HAP_FW_15.05.0108.bin

What's New?

- Fixed the unstable IMU transmission frequency, and put the IMU data into a separate task
- Added IP configurable rule: IP address (A.B.C.D): D cannot be 0, 1 or 255.

A cannot be 0 or 127

A must be less than 224

Mask must be continuous

IP address and gateway cannot be the same

Gateway (A.B.C.D): D cannot be 0 or 255

A cannot be 0 or 127

A must be less than 224

- Fixed some known issues